



AUDI A4: 1FRR630

Vinnnumber:	WAUZZZ8KXEA052693	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	89621	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3524
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	SD	Sun Roof electric
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/94 H LightMetal			
Winter tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1930,08
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Ignition key, Missing, E - Replace

150,00

