


**BMW 1 HATCH: ZG9618**

|                                   |                          |              |                        |
|-----------------------------------|--------------------------|--------------|------------------------|
| Vinnnumber:                       | <b>WBA1V710705A57473</b> | Versionname: | <b>1.5 116D (85KW)</b> |
| First Registrationdate:           | <b>10/06/2015</b>        | Fiscalpower: |                        |
| Expertise Mileage:                | <b>90544</b>             | Power Kw:    | <b>85</b>              |
| Bodytype:                         |                          | Body color   | <b>Black</b>           |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>         |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>       |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>              |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>4614</b>            |
| Number of doors                   | <b>5</b>                 |              |                        |
| Number of seats                   | <b>5</b>                 |              |                        |
| Number head rests                 | <b>5</b>                 |              |                        |
| Rims summer                       | <b>Aluminium</b>         |              |                        |
| Category                          | <b>Passenger Car</b>     |              |                        |
| Oil level                         | <b>OK</b>                |              |                        |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                        |

**Options**

|                                |                              |                  |
|--------------------------------|------------------------------|------------------|
| Radio CD                       |                              | Central consol F |
| GPS storage                    | <b>HD</b>                    | Luggage cover    |
| GPS storage                    |                              |                  |
| Windows electric F             |                              |                  |
| Windows electric R             |                              |                  |
| Cruise Control                 |                              |                  |
| Steering wheel multifunctional |                              |                  |
| Seats F heated                 |                              |                  |
| Radio multimedia               |                              |                  |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                  |
| Type of GPS                    | <b>GPS big screen color</b>  |                  |
| Type of Lining                 | <b>Lining fabrics</b>        |                  |
| Type of climate control        | <b>Autom climate control</b> |                  |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| Winter tyres: | <b>205/55/16/91 H LightMetal</b> |                       |       |                       |
|               | Fr.L.                            | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b> | Re.R. | <b>Michelin: 4 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |               |
|-------------------|---------------|
| Total cost ex VAT | <b>495,56</b> |
|-------------------|---------------|

|                                           |               |
|-------------------------------------------|---------------|
| Bumper F L, Scratch(es), It - Spot repair | <b>115,56</b> |
|-------------------------------------------|---------------|



|                                                              |              |
|--------------------------------------------------------------|--------------|
| Alloy rim R L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--------------------------------------------------------------|--------------|



|                                                              |       |
|--------------------------------------------------------------|-------|
| Door F L, Dent(s), Acceptable                                | 0,00  |
| No pictures to display                                       |       |
| Wing R R, Scratch(es), Acceptable                            | 0,00  |
| No pictures to display                                       |       |
| Wing R R, Dent(s), Acceptable                                | 0,00  |
| No pictures to display                                       |       |
| Wing F R, Dent(s), Acceptable                                | 0,00  |
| No pictures to display                                       |       |
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                               |      |
|-------------------------------|------|
| Door R R, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display