



BMW 3 GRAN TURISMO: 1RBE560			
Vinnnumber:	WBA8T11080BA26350	Versionname:	2.0 318D (100KW) GRAN TURISMO
First Registrationdate:	3/11/2016	Fiscalpower:	
Expertise Mileage:	71915	Power Kw:	100
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4729
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/55/17/97 Y LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			245,00
Bumper R, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00



Tailgate, Dent(s), Acceptable			0,00
No pictures to display			
Door F R, Scratch(es), Acceptable			0,00
No pictures to display			

Ignition key, Missing, E - Replace	150,00
	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	