



BMW 3: 1JNU590

Vinnnumber:	WBA3Y11060D451319	Versionname:	3 GRAN TURISMO 318d 136PK
First Registrationdate:	27/01/2015	Fiscalpower:	
Expertise Mileage:	114152	Power Kw:	100
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel		
Maintenance	NOT OK		
Maintenance	UITVOEREN - 370KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Radio CD	Sun Roof electric
GPS storage	Panoramic roof
GPS storage	HD Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Tires wear profile	OK	Battery functioning	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK		

Degree of wear

	225/50/18/95 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1045,75
Windscreen, Stone chip(s), Windscreen repair	58,80



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80





Maintenance, Maintenance, Execute

0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Interior, Dirty, Chemical cleaning

95,00



Alloy rim R L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Grill, Crack, E - Replace

55,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

