



BMW SERIE 3 TOURING: 1JGP496				
Vinnnumber:	WBA3L11070K258509	Versionname:	320D	
First Registrationdate:	12/12/2014	Fiscalpower:		
Expertise Mileage:	100172	Power Kw:	120	
Bodytype:		Body color	Brown	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Back	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	IN 6000 KM	Parking lot	2532	
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Sun Roof electric		
GPS storage		Panoramic roof		
GPS storage	HD	Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Assistance equipment				
	Runflat		Yes	
Total cost ex VAT			1152,06	
Seat cover F R, Stain, Acceptable			0,00	
No pictures to display				
Wing R R, Dent(s), Acceptable			0,00	
No pictures to display				
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)			307,80	



Boot carpet, Stain, Acceptable	0,00
--------------------------------	------

No pictures to display

Interior, Smell, Ozone treatment	152,58
----------------------------------	--------



Sill trim R, Scratch(es), LI - Repair and paint (partial)	275,00
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Floor covering F L, Burned, Smart repair	64,32
--	-------



Door F R, Scratch(es), It - Spot repair	115,56
---	--------

