



AUDI A3: 1HUP169				
Vinnnumber:	WAUZZZ8V0FA059762	Versionname:	A3 SB Ultra Attraction	
First Registrationdate:	7/10/2014	Fiscalpower:	110PK	
Expertise Mileage:	102806	Power Kw:	81	
Bodytype:	Hatchback	Body color	Blue	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3406	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Rear parking sensors		
Cruise Control		Type of Tow bar	No Tow bar	
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Kleber: 6 mm	Fr.R.	Kleber: 6 mm
	Re.L.	Kleber: 8 mm	Re.R.	Kleber: 8 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			576,50	
Outer backrest protection L, Scratch(es), Acceptable			0,00	
No pictures to display				
Seat cover F R, Stain, Cleaning			0,00	
No pictures to display				
Wing R L, Dent(s), Acceptable			0,00	
No pictures to display				
Steering wheel, Worn, Acceptable			0,00	
No pictures to display				
Door frame R R, Scratch(es), Acceptable			0,00	
No pictures to display				
Sill trim R L, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00	



Door R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)	481,50



Seat cover R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Cleaning	0,00
<i>No pictures to display</i>	