



MERCEDES A: 1KXP392			
Vinnnumber:	WDD1760121V082176	Versionname:	1.5 A 180 CDI
First Registrationdate:	27/07/2015	Fiscalpower:	
Expertise Mileage:	75236	Power Kw:	80
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	SERV B5 IN 330 DAGEN	Parking lot	4514
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	195/65/15/95 V Steel		
	Fr.L.	Michelin: 5 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
		Michelin: 5 mm	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			448,84
Wing F R, Scratch(es), 67 - Polish			0,00



Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rear window, Not original part, Remove lettering	0,00
--	------



Rearview mirror housing R, Scratch(es), Smart repair	110,64
--	--------

