



MERCEDES CLA: 1HTZ334				
Vinnumber:	WDD1173081N141707	Versionname:	CLA BER 200 CDI(EU6)	
First Registrationdate:	2/10/2014	Fiscalpower:	136PK	
Expertise Mileage:	82604	Power Kw:	100	
Bodytype:	Berline	Body color	Black	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	OK			
Maintenance	SERVICE B5 OVER27 DAGEN			
Battery functioning	Yes			
Number of doors	4			
Number of seats	5			
Number head rests	0			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage	HD			
GPS storage				
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	205/40/17/93 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 3 mm	Fr.R.	Kleber: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			2325,50	
Rearview mirror R complete, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00	
				
Door F R, Scratch(es), LI - Repair and paint (complete)			318,35	



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Roof, Dent(s), PDR - Knock out without painting

82,80



Bumper R, Dent(s) and scratch(es), Le - Replace and paint

651,00



Certificate Of Conformity, Missing, E - Replace

150,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80





Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), Windscreen repair 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display