



PEUGEOT 5008: 1DUR325

Vinnnumber:	VF30A9HR8CS195258	Versionname:	5008 Active FAP 112PK
First Registrationdate:	3/09/2012	Fiscalpower:	
Expertise Mileage:	146615	Power Kw:	82
Bodytype:		Body color	Beige
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1112
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H Steel			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	338,20
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Steering wheel, Worn, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Ignition key, Worn, Acceptable	0,00
--------------------------------	-------------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display