



FORD Transit 330L: 1COU170				
Vinnumber:	WF0NXXTTFNBP20756	Versionname:	TRANSIT 330L CH2C LWB RWD DPF(EU5) 100PK	
First Registrationdate:	20/01/2012	Fiscalpower:		
Expertise Mileage:	194537	Power Kw:	74	
Bodytype:	Transporter	Body color	White	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:		Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	LCV04	
Number of doors	4			
Number of seats	6			
Number head rests	6			
Rims summer	Steel			
Category	Light Commercial Vehicle			
Oil level	OK			
Options				
Radio CD		Central consol F		
Windows electric F		Type of Tow bar	Tow bar fixed	
Type of headlighting	Headlighting Halogen			
Type of GPS	No GPS			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	215/75/16/113 R Steel			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm
Assistance equipment				
Spare wheel	Yes			
Total cost ex VAT	1189,71			
Sidewall FL (LCV), Dent(s), Acceptable	0,00			
<i>No pictures to display</i>				
Interior, Dirty, Cleaning	0,00			
 				
Wing R L, Dent(s) and scratch(es), Forfeit	50,00			
 				
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13			



Sidewall FR (LCV), Dent(s) and scratch(es), It - Spot repair 115,56



Tailgate, Dent(s), PDR - Knock out without painting 63,00



Door R R, Scratch(es), LI - Repair and paint (complete) 238,76



Sill outer R, Rust, LI - Repair and paint (complete) 232,88



Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight L, Broken, E - Replace 91,50



Sill outer L, Rust, LI - Repair and paint (complete) 232,88



