



OPEL VIVARO: PF8825			
Vinnumber:	W0L2F7118FV649092	Versionname:	1.6CDTI BI T 88KW
First Registrationdate:	19/08/2015	Fiscalpower:	EDITION S/S LWB 2.9T
Expertise Mileage:	62982	Power Kw:	88
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3222
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	205/65/16/105 T Steel		
	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 5 mm	Re.R.
			Continental: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			638,64
Bumper F, Scratch(es), LI - Repair and paint (complete)			158,85



Trunk door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), E - Replace	69,00



Rearview mirror housing L, Broken, F - Replace	69,00
--	-------

 	
Wheel cover F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bodywork, Not original part, Acceptable	0,00
No pictures to display	
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
 	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Dent(s) and scratch(es), Smart repair	110,64
  	
Interior, Dirty, Acceptable	0,00
No pictures to display	