



MERCEDES CLA SHOOTING BRAKE: 1LRS637				
Vinnumber:	WDD1179421N317752	Versionname:	1.6 CLA 180 URBAN SHOOTING BRAKE	
First Registrationdate:	17/11/2015	Fiscalpower:		
Expertise Mileage:	26291	Power Kw:	90	
Bodytype:		Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Petrol	Oil level	OK	
Maintenance	OK			
Maintenance	SERVICE A0 IN 238D			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	1			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Sun Roof electric		
GPS storage		Panoramic roof		
GPS storage	SD	Central consol F		
Windows electric F		Luggage cover		
Windows electric R				
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT		933,44		
Roof pillar L, Dent(s), PDR - Knock out without painting		63,00		
Bumper trim R, Scratch(es), Smart repair		110,64		



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rearview mirror glass R, Missing, E - Replace	18,00
---	-------



Tyre F R, Deformed / Strained, E - Replace	132,00
--	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rearview mirror glass L, Missing, E - Replace	18,00
---	-------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00

