



OPEL Insignia: 1HVS892

Vinnnumber:	WOLGT8ES8E1168855	Versionname:	INSIGNIA BRE ecoFLEX
First Registrationdate:	15/10/2014	Fiscalpower:	Cosmo 140PK
Expertise Mileage:	151917	Power Kw:	103
Bodytype:	Break	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2129
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			646,80
Ignition key, Worn, E - Replace			150,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), Windscreen repair	0,00
--	------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

