




MERCEDES C: 1FSQ336			
Vinnnumber:	WDD2040001A914807	Versionname:	C BER 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	11/10/2013	Fiscalpower:	
Expertise Mileage:	128090	Power Kw:	88
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4307
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Summer tyres:	195/65/16/89 V LightMetal		
	Fr.L.	Michelin: 4 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.
		Michelin: 4 mm	Michelin: 5 mm
Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1394,60
Door panel R L, Scratch(es), Acceptable			0,00
No pictures to display			
Bumper R, Dent(s) and scratch(es), Le - Replace and paint			651,00
Wing R R, Dent(s), PDR - Knock out without painting			82,80

  		Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
 		Door F R, Dent(s), PDR - Knock out without painting	63,00
 		Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display		Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display		Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
    		Gear shift lever knob, Worn, E - Replace	114,00
 		Door panel F L, Hole, E - Replace	114,00
 		Door F L, Scratch(es), Acceptable	0,00
No pictures to display		Door R L, Dent(s), PDR - Knock out without painting	63,00
 			