



RENAULT Clio: 1HUB021

Vinnumber:	VF17RFL0H50969550	Versionname:	CLIO IV BRE Energy Graphite 90PK
First Registrationdate:	2/10/2014	Fiscalpower:	
Expertise Mileage:	135796	Power Kw:	66
Bodytype:	Hatchback	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2829
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm


Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	884,64
-------------------	--------

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display	
Wheel cover F L, Scratch(es), E - Replace	24,00



Door panel R R, Scratch(es), Smart repair	110,64
---	--------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------



Tailgate, Scratch(es), It - Spot repair

115,56



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Hole, Smart repair

64,32



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Seat cover F L, Dirty, Cleaning

25,00



Door panel F R, Scratch(es), Smart repair

110,64



Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Bonnet, Bad repair, Paint

0,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s), PDR - Knock out without painting

82,80



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bodywork, Glue residues, Remove lettering	25,00
---	-------



Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Broken, E - Replace	24,00
--------------------------------------	-------



Wheel cover F R, Missing, E - Replace	24,00
---------------------------------------	-------

