


PEUGEOT 308: 1EXC188

Vinnnumber:	VF34E9HP0DS050958	Versionname:	308 SW Access 92PK
First Registrationdate:	11/04/2013	Fiscalpower:	
Expertise Mileage:	76866	Power Kw:	68
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	SERVICE -27700KM	Parking lot	2223
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1954,28
-------------------	----------------

Seat cover F L, Stain, E - Replace	360,00
------------------------------------	---------------



Sill outer L, Dent(s), LI - Repair and paint (complete)	358,50
---	---------------



Wheel cover F R, Scratch(es), E - Replace 30,00



Engine protective plate, Hole, E - Replace 69,40



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 283,80



Maintenance, Maintenance, Execute 0,00



Wheel arch cover F L, Broken, E - Replace 82,40



Wheel cover R R, Scratch(es), E - Replace 30,00



Door F L, Repaired, Acceptable 0,00

No pictures to display

Door R L, Repaired, Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
	
Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
	
Door R R, Repaired, Acceptable	0,00
No pictures to display	