



SEAT Alhambra: 1FRL963			
Vinnnumber:	VSSZZZ7NZBV503027	Versionname:	ALHAMBRA
First Registrationdate:	25/09/2012	Ecom.Reference DPF	136PK
Expertise Mileage:	177706	Fiscalpower:	
Bodytype:	SUV	Power Kw:	100
Gearbox:	MAN 6 VIT	Body color	Black
Transmission:		Paint type	Metalic
Fueltype:	Diesel	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	215/60/16/99 H LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment	
Total cost ex VAT	1401,32
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02



Alloy rim R L, Not original part, Acceptable	0,00
--	------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F R, Not original part, Acceptable	0,00
--	------



Bumper F, Scratch(es), It - Spot repair	115,56
---	--------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	--------



Alloy rim R R, Not original part, Acceptable	0,00
--	------



Alloy rim F L, Not original part, Acceptable	0,00
--	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Rearview mirror housing L, Broken, Repair/replace (lump sum)	20,00
--	-------



Rearlight L, Broken, E - Replace	132,00
----------------------------------	--------

