


RENAULT Trafic: 1EVP977

Vinnnumber:	VF1FLA0AEDY490973	Versionname:	TRAFIC 27 B/F L1H1
First Registrationdate:	2/04/2013	Fiscalpower:	Gr.Conf.FAP(E5)90PK
Expertise Mileage:	31684	Power Kw:	66
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2604
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Rear parking sensors
Windows electric F	Type of Tow bar
Radio multimedia	Tow bar fixed
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/16/105 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1267,78
-------------------	----------------

Bumper corner R R, Broken, E - Replace	64,00
--	--------------



Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Bumper corner R L, Scratch(es), Smart repair	110,64
--	---------------



Bumper F, Scratch(es), Smart repair	125,64
-------------------------------------	---------------



Sliding door R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Trunk door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	217,56



Door F L, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Wheel covers (all), Missing, E - Replace	88,00
--	-------



Sidewall RL (LCV), Dent(s) and scratch(es), It - Spot repair	115,56
--	--------



Trunk door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Wing R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror glass L, Missing, E - Replace	13,50



Sill outer R, Dent(s), PDR - Knock out without painting

63,00

