



RENAULT Traffic: 1EVQ215				
Vinnumber:	VF1FLA0AEDY490917	Versionname:	TRAFIC 27 B/F L1H1	
First Registrationdate:	2/04/2013	Fiscalpower:	Gr.Conf.FAP(E5)90PK	
Expertise Mileage:	62401	Power Kw:	66	
Bodytype:	Transporter	Body color	Grey	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Maintenance	OK	Parking lot	2633	
Battery functioning	Yes			
Number of doors	5			
Number of seats	3			
Number head rests	3			
Rims summer	Steel			
Category	Light Commercial Vehicle			
Oil level	OK			
Registration Certificate Car (BE)	No			
Options				
Radio CD		Type of Tow bar	Tow bar fixed	
Windows electric F				
Type of headlighting	Headlighting Halogen			
Type of GPS	No GPS			
Type of Lining	Lining fabrics			
Type of climate control	Manual climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
	205/65/16/105 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			2063,58	
Wheel cover R L, Missing, E - Replace			22,50	
				
Steering wheel, Worn, Acceptable			0,00	
No pictures to display				
Rearview mirror housing L, Scratch(es), Acceptable			0,00	
No pictures to display				
Trunk door panel R, Scratch(es), Acceptable			0,00	
No pictures to display				
Interior, Dirty, Cleaning			50,00	



Trunk door R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Trunk door R L, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Bodywork, Glue residues, Remove lettering	150,00



Door F L, Dent(s), Acceptable	0,00
No pictures to display	
Wheel cover F R, Missing, E - Replace	22,50



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	375,15
---	--------



Wheel cover R R, Missing, E - Replace	22,50
---------------------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
No pictures to display	

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 286,76



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete) 361,13



Door moulding Lower R R, Scratch(es), E - Replace 91,50



Bumper F, Dent(s) and scratch(es), E - Replace 398,40



Wheel cover F L, Missing, E - Replace 22,50



Ignition key, Worn, E - Replace 150,00



Rearview mirror housing R, Scratch(es), Smart repair 110,64



Trunk door panel L, Scratch(es), Acceptable 0,00

<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	