



SKODA Octavia: 1BWG025			
Vinnnumber:	TMBCT21Z3C2047142	Versionname:	OCTAVIA BER Ambiente
First Registrationdate:	20/09/2011	Fiscalpower:	DPF DSG 105PK Aut.
Expertise Mileage:	133099	Power Kw:	77
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	IN 2300KM	Parking lot	4229
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/91 H Steel			
	Fr.L.	Michelin: 8 mm	Fr.R.	Michelin: 8 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Emergency spare wheel	Yes
Jack	Yes
Total cost ex VAT	871,59
Door R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Stain, Cleaning	25,00
<i>No pictures to display</i>	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35



Door frame R L, Scratch(es), It - Spot repair	115,56
---	---------------

			
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)			301,68
			
Door F L, Dent(s), PDR - Knock out without painting			111,00

