


RENAULT Megane: 1EBZ329

Vinnnumber:	VF1BZ1A0747842248	Versionname:	MEGANE BER Business
First Registrationdate:	16/10/2012	Fiscalpower:	90PK
Expertise Mileage:	50511	Power Kw:	66
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1110
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1705,69
-------------------	---------

Wheel cover R R, Scratch(es), E - Replace	30,00
---	-------



Wheel cover F L, Scratch(es), E - Replace	30,00
---	-------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wheel cover F R, Scratch(es), E - Replace

30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Mirror side blinker L, Missing, E - Replace

30,00



Tailgate, Dent(s), Acceptable

0,00

Front gate, Dent(s), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover R L, Scratch(es), Acceptable	0,00
No pictures to display	