



|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| PEUGEOT Expert: KG9833  |                          |              |                              |
| Vinnnumber:             | VF3XS9HM0EZ020700        | Versionname: | EXPERT B/F SWB 227 L1H1 90PK |
| First Registrationdate: | 11/06/2014               | Fiscalpower: |                              |
| Expertise Mileage:      | 186052                   | Power Kw:    | 66                           |
| Bodytype:               | Transporter              | Body color   | White                        |
| Gearbox:                | MAN 5 VIT                | Paint type   | Metalic                      |
| Transmission:           |                          | Rims summer  | Steel                        |
| Fueltype:               | Diesel                   | Oil level    | OK                           |
| Battery functioning     | Yes                      | Parking lot  | 3403                         |
| Number of doors         | 5                        |              |                              |
| Number of seats         | 3                        |              |                              |
| Number head rests       | 3                        |              |                              |
| Rims summer             | Steel                    |              |                              |
| Category                | Light Commercial Vehicle |              |                              |
| Oil level               | OK                       |              |                              |

|                         |                           |                      |               |
|-------------------------|---------------------------|----------------------|---------------|
| Options                 |                           |                      |               |
| Radio CD                |                           | Rear parking sensors |               |
| Windows electric F      |                           | Type of Tow bar      | Tow bar fixed |
| Radio multimedia        |                           |                      |               |
| Type of headlighting    | Headlighting Halogen      |                      |               |
| Type of GPS             | No GPS                    |                      |               |
| Type of Lining          | Lining artificial leather |                      |               |
| Type of climate control | Manual climate control    |                      |               |

|                              |    |                     |        |
|------------------------------|----|---------------------|--------|
| Limited Technical Inspection |    |                     |        |
| Airco functioning            | OK | Battery functioning | Yes    |
| Tires wear profile           | OK | Power steering      | Yes    |
| Idle position                | OK | Sound engine        | OK     |
| Engine startingtime          | OK | Clutch test         | OK     |
| Exhaust gass                 | OK | Wiper fluid level   | NOT OK |
| Handbrake                    | OK | Transmission        | OK     |
|                              |    | Lighting            | OK     |
|                              |    | Wiperblades         | OK     |

|                |                       |                 |       |                 |
|----------------|-----------------------|-----------------|-------|-----------------|
| Degree of wear |                       |                 |       |                 |
| Summer tyres:  | 215/65/15/104 T Steel |                 |       |                 |
|                | Fr.L.                 | Michelin: 3 mm  | Fr.R. | Michelin: 3 mm  |
|                | Re.L.                 | Firestone: 7 mm | Re.R. | Firestone: 7 mm |

|                                             |        |
|---------------------------------------------|--------|
| Assistance equipment                        |        |
| Spare wheel                                 | Yes    |
| Total cost ex VAT                           | 620,41 |
| Outer door handle R R, Missing, E - Replace | 10,00  |



|                                                                     |        |
|---------------------------------------------------------------------|--------|
| Sidewall FL (LCV), Scratch(es), Acceptable                          | 0,00   |
| No pictures to display                                              |        |
| Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 165,13 |





|                                    |        |
|------------------------------------|--------|
| Ignition key, Missing, E - Replace | 150,00 |
|------------------------------------|--------|

No pictures to display

|                                     |        |
|-------------------------------------|--------|
| Bumper F, Scratch(es), Smart repair | 110,64 |
|-------------------------------------|--------|



|                                         |       |
|-----------------------------------------|-------|
| Trunk door panel L, Broken, E - Replace | 74,00 |
|-----------------------------------------|-------|



|                                                 |        |
|-------------------------------------------------|--------|
| Bumper R, Dent(s) and scratch(es), Smart repair | 110,64 |
|-------------------------------------------------|--------|



|                                   |      |
|-----------------------------------|------|
| Sill outer L, Dent(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display