



MINI Countryman: 1FSE190			
Vinnumber:	WMWZD11090WL32965	Versionname:	MINI COUNTRYMAN One D DPF 90PK
First Registrationdate:	8/10/2013	Fiscalpower:	
Expertise Mileage:	151431	Power Kw:	66
Bodytype:	Hatchback	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1118
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunction	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 3 mm	Re.R.	Uniroyal: 3 mm

Assistance equipment	
Repair kit	No
Total cost ex VAT	938,13
Bumper R, Dent(s), LI - Repair and paint (complete)	211,80



Bumper F, Dent(s), LI - Repair and paint (complete)	211,80
---	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display	
Tyre repair kit, Missing, E - Replace	210,53
	
Door R L, Dent(s), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Windscreen, Repaired, Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door moulding Lower R L, Scratch(es), E - Replace	114,00
	