



RENAULT TALISMAN GRANDTOUR: 1PVS896

|                                   |                   |              |                           |
|-----------------------------------|-------------------|--------------|---------------------------|
| Vinnnumber:                       | VF1RFD00056510820 | Versionname: | 1.5 DCI 110 ENERGY INTENS |
| First Registrationdate:           | 30/09/2016        | Fiscalpower: |                           |
| Expertise Mileage:                | 206182            | Power Kw:    | 81                        |
| Bodytype:                         | Break             | Body color   | Grey                      |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic                   |
| Transmission:                     |                   | Rims summer  | Aluminium                 |
| Fueltype:                         | Diesel            | Oil level    | OK                        |
| Battery functioning               | Yes               |              |                           |
| Number of doors                   | 5                 |              |                           |
| Number of seats                   | 5                 |              |                           |
| Number head rests                 | 5                 |              |                           |
| Rims summer                       | Aluminium         |              |                           |
| Category                          | Passenger Car     |              |                           |
| Oil level                         | OK                |              |                           |
| Registration Certificate Car (BE) | Yes               |              |                           |

Options

|                                |                       |
|--------------------------------|-----------------------|
| Windows electric F             | Central consol F      |
| Windows electric R             | Luggage cover         |
| Cruise Control                 | Rear parking sensors  |
| Steering wheel multifunctional | Type of Tow bar       |
| Radio multimedia               | No Tow bar            |
| Type of headlighting           | Headlighting Xenon    |
| Type of GPS                    | GPS big screen color  |
| Type of Lining                 | Lining semi-leather   |
| Type of climate control        | Autom climate control |

Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

Degree of wear

|               |                            |                |       |                |
|---------------|----------------------------|----------------|-------|----------------|
| Summer tyres: | 225/55/17/101 Y LightMetal |                |       |                |
|               | Fr.L.                      | Uniroyal: 4 mm | Fr.R. | Uniroyal: 4 mm |
|               | Re.L.                      | Uniroyal: 5 mm | Re.R. | Uniroyal: 5 mm |
|               |                            |                |       |                |

Assistance equipment

|                                             |  |        |
|---------------------------------------------|--|--------|
| Compressor                                  |  | Yes    |
| Total cost ex VAT                           |  | 481,76 |
| Bumper F, Deformed / Strained, Smart repair |  | 110,64 |



|                                    |       |
|------------------------------------|-------|
| Seat cover F L, Hole, Smart repair | 64,32 |
|------------------------------------|-------|



|                                        |      |
|----------------------------------------|------|
| Alloy rim F L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

|                                                                                    |        |
|------------------------------------------------------------------------------------|--------|
| No pictures to display                                                             |        |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete)                       | 95,00  |
|  |        |
| Wing R R, Scratch(es), 67 - Polish                                                 | 0,00   |
| No pictures to display                                                             |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete)                            | 211,80 |
|  |        |
| Bumper F, Dent(s) and scratch(es), Acceptable                                      | 0,00   |
| No pictures to display                                                             |        |
| Tailgate, Scratch(es), 67 - Polish                                                 | 0,00   |
| No pictures to display                                                             |        |
| Door F R, Scratch(es), Acceptable                                                  | 0,00   |
| No pictures to display                                                             |        |