



|                         |                   |              |                         |
|-------------------------|-------------------|--------------|-------------------------|
| RENAULT Laguna: TM7340  |                   |              |                         |
| Vinnnumber:             | VF1KT1RG647805626 | Versionname: | LAGUNA BRE Bose Edition |
| First Registrationdate: | 20/01/2014        |              | 110PK                   |
| Expertise Mileage:      | 120016            | Fiscalpower: |                         |
| Bodytype:               | Break             | Power Kwr:   | 81                      |
| Gearbox:                | MAN 6 VIT         | Body color   | Silver                  |
| Transmission:           |                   | Paint type   | Metalic                 |
| Fueltype:               | Diesel            | Rims summer  | Aluminium               |
| Battery functioning     | Yes               | Oil level    | OK                      |
| Number of doors         | 5                 | Parking lot  | 2301                    |
| Number of seats         | 5                 |              |                         |
| Number head rests       | 5                 |              |                         |
| Rims summer             | Aluminium         |              |                         |
| Category                | Passenger Car     |              |                         |
| Oil level               | OK                |              |                         |

|                                |                       |                      |            |
|--------------------------------|-----------------------|----------------------|------------|
| Options                        |                       |                      |            |
| Radio CD                       |                       | Central consol F     |            |
| Windows electric F             |                       | Luggage cover        |            |
| Windows electric R             |                       | Rear parking sensors |            |
| Cruise Control                 |                       | Type of Tow bar      | No Tow bar |
| Steering wheel multifunctional |                       |                      |            |
| Radio multimedia               |                       |                      |            |
| Type of headlighting           | Headlighting Halogen  |                      |            |
| Type of GPS                    | GPS big screen color  |                      |            |
| Type of Lining                 | Lining semi-leather   |                      |            |
| Type of climate control        | Autom climate control |                      |            |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                   |       |                   |
|----------------|---------------------------|-------------------|-------|-------------------|
| Degree of wear |                           |                   |       |                   |
| Summer tyres:  | 215/50/17/95 W LightMetal |                   |       |                   |
|                | Fr.L.                     | Bridgestone: 6 mm | Fr.R. | Bridgestone: 6 mm |
|                | Re.L.                     | Continental: 5 mm | Re.R. | Continental: 5 mm |
|                |                           |                   |       |                   |

|                                        |     |      |      |
|----------------------------------------|-----|------|------|
| Assistance equipment                   |     |      |      |
| Spare wheel                            | Yes | Jack | Yes  |
| Total cost ex VAT                      |     |      | 0,00 |
| Door F L, Scratch(es), Acceptable      |     |      | 0,00 |
| No pictures to display                 |     |      |      |
| Alloy rim R R, Scratch(es), Acceptable |     |      | 0,00 |
| No pictures to display                 |     |      |      |