







## RENAULT Grand Scenic: 1HRN775

Vinnumber: VF1JZ14M651469527 First Registrationdate: 15/09/2014 Expertise Mileage: 174964 Bodytype: MPV Gearbox: MAN 6 VIT Transmission: Front Fueltype: Diesel Battery functioning Yes Number of doors 5 Number of seats 5 Number head rests 5 Rims summer Aluminium Category Passenger Car Oil level Registration Certificate Car (BE) Yes

Versionname: GRAND SCENIC Energy Intens 5pl.110PK

 Power Kw:
 81

 Body color
 Brown

 Paint type
 Metalic

 Rims summer
 Aluminium

 Oil level
 OK

#### Options

Radio CD Sun Roof electric

GPS storage SD Central consol F

GPS storage Luggage cover

Windows electric F Front parking sensors

Windows electric R Rear parking sensors

Cruise Control

Steering wheel multifunctional

Seats F heated Radio multimedia

Type of headlighting
Type of GPS
Type of
Lining
Type of climate
Control

Type of climate
Control

Type of climate
Control

Headlighting Xenon
GPS big screen color
Alternative and Climate
Color big screen color
GPS big screen color
GPS big screen color
GPS big screen color
Alternative and Climate
Color big screen color
Alternative and Climate
Color big screen color
GPS big screen color
Alternative and Climate
Color big screen color
Alternative and Climate
Color big screen color
Alternative and Climate
Color big screen color
CPS big screen color
Alternative and Climate
Color big screen color
CPS big screen color

# Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ок
		Lighting	ок
		Wiperblades	OK

## Degree of wear

### Assistance equipment

Spare wheel	Yes Jack	Yes
Total cost ex VAT		362,40
Rearview mirror housing L, Scratch(es), Acceptable		0,00











Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00





Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00





Door F L, Dent(s), PDR - Knock out without painting

63,00





Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Door R L, Scratch(es), Acceptable

0,00



