



VOLKSWAGEN GOLF VII: 1PBK679

Vinnnumber:	WVWZZZAUZGW264451	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	30/05/2016	Fiscalpower:	DSG
Expertise Mileage:	19254	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	2422
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Type of Tow bar Tow bar fixed
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting Headlighting Halogen	
Type of Lining Lining fabrics	
Type of climate control Manual climate control	
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Hankook: 3 mm	Fr.R.	Hankook: 3 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 341,80

Bodywork, Not original part, Remove lettering 0,00



Maintenance, Maintenance, Execute 0,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 50,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 50,00



Electricity circuit, Not functioning (well), Diagnosis 0,00



Floor covering F R, Damaged, Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display