



**VOLKSWAGEN GOLF VII: 1PBK698**

Vinnumber:	<b>WVWZZZAUZGP111493</b>	Versionname:	<b>1.6 TDI 66KW TRENDLINE</b>
First Registrationdate:	<b>30/05/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>29066</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1213</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Luggage cover
Cruise Control	Type of Tow bar <b>Tow bar fixed</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting <b>Headlighting Halogen</b>	
Type of Lining <b>Lining fabrics</b>	
Type of climate control <b>Manual climate control</b>	
Adaptive cruise control	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>679,00</b>
-------------------	---------------

Interior, Stain, Acceptable	<b>0,00</b>
-----------------------------	-------------



Bodywork, Not original part, Remove lettering	<b>0,00</b>
---	-------------



Door F R, Dent(s), Acceptable 0,00

No pictures to display

Roof pillar L, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 235,80



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), PDR - Knock out without painting 63,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 356,20



Backrest cover R L, Strained , Forfeit 24,00



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display