



TOYOTA AYGO: DB1205

Vinnnumber:	JTDKGN50N136731	Versionname:	1.0 VVT-I X-PLAY MMT
First Registrationdate:	7/01/2016	Fiscalpower:	
Expertise Mileage:	62583	Power Kw:	51
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2810
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F		Luggage cover	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	165/60/15/77 H Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2266,48
--------------------------	----------------

Wheel cover F R, Scratch(es), E - Replace	24,00
--	--------------



Door R R, Scratch(es), Acceptable	0,00
--	-------------


No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
--	---------------





Roof, Scratch(es), LI - Repair and paint (complete) 385,20



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 294,56



Sill outer R, Dent(s), LI - Repair and paint (complete) 296,40



Aerial, Missing, E - Replace 12,00



Rocker panel inner R L, Scratch(es), Forfeit 115,56



Wing R R, Scratch(es), LI - Repair and paint (complete) 246,56



Bumper R, Scratch(es), It - Spot repair 115,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 294,56

Wheel cover F L, Scratch(es), E - Replace

24,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Windscreen, Stone chip(s), E - Replace

413,76

