



VOLKSWAGEN GOLF VII: 1PRC383

Vinnumber:	VVWZZZAUZHWO00712	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	29/08/2016	Fiscalpower:	
Expertise Mileage:	30013	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2332
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	Type of Tow bar No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting Headlighting Halogen	
Type of Lining Lining fabrics	
Type of climate control Manual climate control	
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Hankook: 7 mm	Fr.R.	Hankook: 7 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1411,00
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display	
Wing R, Dent(s) and scratch(es), LI - Repair and paint (complete)	428,20



Wheel cover F L, Missing, E - Replace 30,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Acceptable 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 30,00



Bodywork, Not original part, Remove lettering 0,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Broken, Le - Replace and paint 651,00



Wheel cover R L, Missing, E - Replace 30,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Missing, E - Replace 30,00

