



SKODA Octavia: 1HAU111			
Vinnumber:	TMBJG7NE4E0228314	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	5/06/2014	Fiscalpower:	105PK
Expertise Mileage:	69621	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4831
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	N.D.	Re.R.	N.D.

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			862,11
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			308,20

			
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover R L, Not original part, E - Replace			30,00



Wheel cover F L, Not original part, E - Replace 30,00



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover R R, Not original part, E - Replace 30,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Outer door handle R R, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Not original part, E - Replace 30,00

