



VOLKSWAGEN Sharan: 1GMZ863

Vinnnumber:	WVWZZZ7NZEV022047	Versionname:	SHARAN Comfortline BMT
First Registrationdate:	14/03/2014	Fiscalpower:	115PK
Expertise Mileage:	223585	Power Kw:	85
Bodytype:	MPV	Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Black
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	.
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	3326,99
Ignition key, Missing, E - Replace	150,00



Bumper R, Dent(s) and scratch(es), Le - Replace and paint	651,00
---	---------------



Door R R, Dent(s) and scratch(es), Acceptable 0,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Outer door handle R L, Scratch(es), LI - Repair and paint (complete) 115,56



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper F, Broken, Le - Replace and paint 735,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Dent(s), LI - Repair and paint (complete) 366,35



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Door F L, Dent(s), LI - Repair and paint (complete) 462,35

