



AUDI A6: 1ALG458

Vinnumber:	WAUZZZ4F2BN056380	Versionname:	A6 AVANT DPF Multitr.163PK
First Registrationdate:	2/02/2011	Fiscalpower:	
Expertise Mileage:	176967	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3311
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

GPS storage	HD	Sun Roof electric
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Transmission	OK
Handbrake	OK	Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			1114,62
Door R R, Dent(s), PDR - Paintless dent repair			82,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Window R L door, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	430,02
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Tyre repair kit, Missing, E - Replace	252,64
---------------------------------------	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display