



VOLKSWAGEN Caddy: 1GAP709			
Vinnnumber:	WV1ZZZ2KZEX041348	Versionname:	CADDY MAXI VAN B/F 102PK
First Registrationdate:	9/12/2013	Fiscalpower:	
Expertise Mileage:	134300	Power Kw:	75
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3711
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining semi-artificial leather		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/95 T Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1227,49
Supplementary brake lights, Broken, E - Replace			33,00

	Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)	382,02
--	--	---------------





Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Sidewall FL (LCV), Dent(s) and scratch(es), It - Spot repair	115,56
--	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Trunk door R L, Dent(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------

