



VOLKSWAGEN Polo: 1HFB592

Vinnnumber:	WVWZZZ6RZFY070235	Versionname:	POLO Trendline BMT 90PK
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	100622	Power Kw:	66
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2303
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	175/70/14/84 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	587,26
-------------------	---------------

Bumper F, Scratch(es), LI - Repair and paint (complete)	169,44
---	---------------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (complete) 248,40



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44

