



VOLVO V60: 1FAX653

Vinnumber:	YV1FW84A1D1139701	Versionname:	V60 D2 Kinetic St/St
First Registrationdate:	13/05/2013	Fiscalpower:	115PK
Expertise Mileage:	172341	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3627
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	854,50
-------------------	---------------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rocker panel inner F R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	235,80
---	--------



Rocker panel inner F L, Dent(s), Acceptable	0,00
---	------

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------

