



MERCEDES CLA: 1HTA644

Vinnumber:	WDD1173121N142016	Versionname:	DIESEL
First Registrationdate:	25/09/2014	Fiscalpower:	
Expertise Mileage:	151296	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4211
Maintenance:	B6 6100KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Type of headlighting: Headlighting Halogen	
Type of Lining: Lining semi-artificial leather	
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 Y LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	832,24
-------------------	--------








Door panel F L, Scratch(es), Acceptable	0,00
---	------



Door panel F R, Tear, E - Replace	114,00
-----------------------------------	--------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

		
Bumper F, Scratch(es), It - Spot repair		115,56
		
Seat cover R, Stain, Cleaning		50,00
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)		301,68
		
Wing R R, Dent(s), PDR - Paintless dent repair		63,00
		
Door F R, Dent(s), Acceptable		0,00
		
Mirror side blinker L, Broken, E - Replace		30,00
		
Door panel R L, Scratch(es), Acceptable		0,00
		
Roof pillar R, Dent(s), PDR - Paintless dent repair		63,00



Seat cover F L, Worn, P - Check

0,00



Dashboard, Scratch(es), Acceptable

0,00



Door panel R R, Scratch(es), Acceptable

0,00



Door R R, Scratch(es), Acceptable

0,00

