



BMW 3: 1HAG024

Vinnumber:	WBA3D91030J414451	Versionname:	3 BER 316d 116PK
First Registrationdate:	3/06/2014	Fiscalpower:	
Expertise Mileage:	129394	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 3000 KM	Parking lot:	4703
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	570,80
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	-------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door panel R L, Hole, E - Replace 114,00



Wing R L, Dent(s), Acceptable 0,00

