



BMW X4: SC3130

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | WBAXX110900R35996 | Versionname: | 2.0 XDRIVE20D (140KW) |
| First Registrationdate: | 7/10/2015 | Fiscalpower: | 4WD |
| Expertise Mileage: | 84905 | Power Kw: | 140 |
| Bodytype: | | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | 4 Weel | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2125 |
| Maintenance: | IN 25000KM | | |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | No | | |

Options

| | |
|--------------------------------|---------------------------------|
| Radio CD | Central consol F |
| GPS storage | Luggage cover |
| GPS storage | HD Front parking sensors |
| Windows electric F | Rear parking sensors |
| Windows electric R | Type of Tow bar |
| Cruise Control | No Tow bar |
| Steering wheel multifunctional | |
| Seats F heated | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|--------------------------|-------|--------------------------|
| | 245/50/18/100 W LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 8 mm | Fr.R. | Bridgestone: 8 mm |
| | Re.L. | Bridgestone: 8 mm | Re.R. | Bridgestone: 8 mm |

Assistance equipment

| | | |
|--|---------|------------|
| | Runflat | Yes |
|--|---------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 762,02 |
|-------------------|---------------|

| | |
|---|---------------|
| Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 382,02 |
|---|---------------|





Alloy rim R R polished, Rust, LI - Repair and paint (complete) 95,00



Backrest cover F L, Worn, Acceptable 0,00



Alloy rim F R polished, Rust, LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Rust, LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Rust, LI - Repair and paint (complete) 95,00

