



**CITROEN Berlingo: GS7374**

Vinnumber:	<b>VF77B9HF0DN535335</b>	Versionname:	<b>BERLINGO B/F Kort Fresh</b>
First Registrationdate:	<b>12/09/2013</b>	Fiscalpower:	<b>90PK</b>
Expertise Mileage:	<b>152327</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4426</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Type of Tow bar	<b>No Tow bar</b>
Windows electric F		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>No GPS</b>	
Type of Lining:	<b>Lining fabrics</b>	
Type of climate control:	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 2 mm</b>	Fr.R.	<b>Goodyear: 2 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1306,80</b>
<b>Wheel covers (all), Missing, E - Replace</b>	<b>90,00</b>



<b>Rearview mirror housing R, Broken, E - Replace</b>	<b>64,00</b>
---	--------------



<b>Wing F R, Scratch(es), It - Spot repair</b>	<b>115,56</b>
--	---------------



Bonnet, Dent(s), PDR - Paintless dent repair 63,00



Door moulding Lower R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Trunk door R L, Dent(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Scratch(es), It - Spot repair 115,56



Bumper F, Scratch(es), Smart repair 110,64



Seat cover F L, Hole, Smart repair 64,32



Bumper R, Broken, E - Replace 329,40



Sill outer L, Dent(s) and scratch(es), It - Spot repair 115,56



Bodywork, Not original part, Acceptable 0,00

*No pictures to display*