



CITROEN C4 Picasso: 1HXA822

Vinnumber:	VF73A9HC8EJ786899	Versionname:	GR.C4 PICASSO Business
First Registrationdate:	17/10/2014	Fiscalpower:	GPS 115PK
Expertise Mileage:	123965	Power Kw:	85
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2412
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	688,38
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Bad repair, Acceptable	0,00



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	235,80
---	--------



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover F L, Stain, Cleaning	12,50
---------------------------------	-------



Door F R, Bad repair, Acceptable	0,00
----------------------------------	------

