


**CITROEN C4 Picasso: 1JAY949**

Vinnnumber:	<b>VF73A9HC8EJ824096</b>	Versionname:	<b>GR.C4 PICASSO Seduction</b>
First Registrationdate:	<b>20/11/2014</b>	Fiscalpower:	<b>ETG 115PK Aut.</b>
Expertise Mileage:	<b>121377</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Body color:	<b>BLAUW</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Maintenance:	<b>OK</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3606</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		
Adaptive cruise control			

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

205/60/16/92 H LightMetal				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Repair kit	<b>No</b>	Runflat	<b>No</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	2205,92
-------------------	---------

Seat cover F L, Stain, Cleaning	25,00
---------------------------------	-------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Compressor, Missing, E - Replace 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 406,50



Registration Document, Missing, E - Replace	150,00
<i>No pictures to display</i>	
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	342,35
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	235,80
Door F L, Scratch(es), 67 - Polish	0,00
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00