



FORD Galaxy: 1FJV810

Vinnumber:	WF0MXXGBWMDA52320	Versionname:	GALAXY Econetic Trend St&St DPF 115PK
First Registrationdate:	19/07/2013	Fiscalpower:	
Expertise Mileage:	45911	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	GEEN MELDING	Parking lot:	2720
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment










Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1422,41
-------------------	----------------

Door F R, Dent(s), PDR - Paintless dent repair	159,00
--	---------------



Door trim F R, Crack, E - Replace	132,00
-----------------------------------	---------------

	Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
	Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Mirror side blinker R, Scratch(es), E - Replace	31,20
	Wing R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	336,21
	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
	Protection plate M, Hole, E - Replace	45,00
	Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,16
	Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		