



**LU Audi q5: BB8881**

|                                    |                          |              |                             |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnumber:                         | <b>WAUZZ28RXFA096935</b> | Versionname: | <b>2.0 TDI CLEAN DIESEL</b> |
| First Registrationdate:            | <b>4/02/2016</b>         | Fiscalpower: | <b>110KW</b>                |
| Expertise Mileage:                 | <b>124912</b>            | Power Kw:    | <b>110</b>                  |
| Bodytype:                          |                          | Body color:  | <b>Grey</b>                 |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>            |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>2208</b>                 |
| Maintenance:                       | <b>IN 28000KM</b>        |              |                             |
| Battery functioning:               | <b>Yes</b>               |              |                             |
| Number of doors:                   | <b>5</b>                 |              |                             |
| Number of seats:                   | <b>5</b>                 |              |                             |
| Number head rests:                 | <b>5</b>                 |              |                             |
| Rims summer:                       | <b>Aluminium</b>         |              |                             |
| Category:                          | <b>Passenger Car</b>     |              |                             |
| Oil level:                         | <b>OK</b>                |              |                             |
| Registration Certificate Car (BE): | <b>No</b>                |              |                             |

**Options**

|                                |                              |                       |                   |
|--------------------------------|------------------------------|-----------------------|-------------------|
| Radio CD                       |                              | Sun Roof electric     |                   |
| GPS storage                    | <b>HD</b>                    | Panoramic roof        |                   |
| GPS storage                    |                              | Central consol F      |                   |
| Windows electric F             |                              | Luggage cover         |                   |
| Windows electric R             |                              | Front parking sensors |                   |
| Cruise Control                 |                              | Rear parking sensors  |                   |
| Steering wheel multifunctional |                              | Type of Tow bar       | <b>No Tow bar</b> |
| Seats F heated                 |                              |                       |                   |
| Type of headlighting           | <b>Headlighting Xenon</b>    |                       |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                       |                   |
| Type of Lining                 | <b>Lining leather</b>        |                       |                   |
| Type of climate control        | <b>Autom climate control</b> |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>235/65/17/104 W LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                             | <b>Goodyear: 3 mm</b> | Fr.R. | <b>Goodyear: 3 mm</b> |
|               | Re.L.                             | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                          |               |
|--------------------------|---------------|
| <b>Total cost ex VAT</b> | <b>317,16</b> |
|--------------------------|---------------|

|  |               |
|--|---------------|
| <b>Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)</b> | <b>254,16</b> |
|--|---------------|





Door R L, Dent(s), PDR - Paintless dent repair 63,00

