


FORD RANGER: 1NXP161

Vinnumber:	6FPPXXMJ2PGB44597	Versionname:	
First Registrationdate:	17/05/2016	Fiscalpower:	
Expertise Mileage:	75130	Power Kw:	118
Bodytype:		Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4728
Maintenance:	UITVOEREN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Front parking sensors	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

265/60/18/110 T LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	No	Jack	No
-------------	-----------	------	-----------

Total cost ex VAT	2069,68
-------------------	---------

Door frame F L, Dent(s), It - Spot repair	115,56
---	--------



Bumper corner R R, Scratch(es), It - Spot repair	115,56
--	--------



Jack, Missing, E - Replace 42,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair 115,56



Interior, Dirty, Chemical cleaning 0,00



Wing R R, Dent(s), PDR - Paintless dent repair 63,00



Door F L, Dent(s), PDR - Paintless dent repair 63,00



Mirror side blinker L, Missing, E - Replace 31,20



Interior, Smell, Ozone treatment 152,58



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 362,02



Seat cover F L, Hole, E - Replace	408,00
-----------------------------------	--------



Spare wheel, Missing, E - Replace	231,36
-----------------------------------	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

