



FORD TRANSIT: 1GBS821

Vinnumber:	WFOZXXTTGZDD14033	Versionname:	
First Registrationdate:	18/12/2013	Fiscalpower:	
Expertise Mileage:	188172	Power Kw:	74
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV24
Battery functioning:	No		
Number of doors:	5		
Number of seats:	6		
Number head rests:	6		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	No
Tires wear profile	OK	Power steering	No
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	NOT OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	NOT OK
		Wiperblades	NOT OK

Degree of wear

	215/65/15/104 T Steel			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2045,19
-------------------	---------

Roof, Dent(s), LI - Repair and paint (complete)	457,13
---	--------



Tailgate, Deformed / Strained, Acceptable	0,00
---	------

No pictures to display

Tailgate, Dent(s) and scratch(es), Le - Replace and paint	799,99
---	--------



Steering column top cover, Missing, E - Replace 198,00



Molding trunk, Crack, E - Replace 27,00



Wing R R, Dent(s), LI - Repair and paint (complete) 231,15



Rearview mirror housing L, Scratch(es), Smart repair 110,64



Bumper R, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Smart repair 110,64

