



FORD Focus: 1FDE057			
Vinnumber:	<b>WF0LXXGCBLDB64254</b>	Versionname:	<b>FOCUS CLIP. ECONetic T.Titanium 115PK</b>
First Registrationdate:	<b>29/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>142206</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4731</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>215/55/16/93 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 2 mm</b>	Fr.R.	<b>Kleber: 2 mm</b>
	Re.L.	<b>Continental: 2 mm</b>	Re.R.	<b>Continental: 2 mm</b>


Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			294,50
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Floor covering F L, Burned, Smart repair			64,32



Reflector, Broken, E - Replace	10,00
--------------------------------	-------



Door F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Not functioning (well), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Dent(s), LI - Repair and paint (complete)	220,18



Brand badge R, Worn, Acceptable	0,00
<i>No pictures to display</i>	