



<b>PEUGEOT 3008: 1EVN556</b>			
Vinnumber:	<b>VF30U9HD8DS043422</b>	Versionname:	<b>3008 Allure FAP 115PK</b>
First Registrationdate:	<b>1/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>147524</b>	Power Kw:	<b>84</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3423</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

<b>Options</b>			
Radio CD		Panoramic roof	
GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>215/60/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 3 mm</b>	Fr.R.	<b>Kleber: 3 mm</b>
	Re.L.	<b>Kleber: 4 mm</b>	Re.R.	<b>Kleber: 4 mm</b>

<b>Assistance equipment</b>			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>1559,80</b>
<b>Bumper trim R, Dent(s) and scratch(es), E - Replace</b>			<b>149,00</b>



<b>Bonnet, Chemical polution, LI - Repair and paint (complete)</b>	<b>290,08</b>
--	---------------



Door seal F R, Deformed / Strained, E - Replace 54,00



Headlight R, Crack, E - Replace 396,00



Bumper R, Scratch(es), It - Spot repair 115,56



Wing R L, Chemical polution, LI - Repair and paint (complete) 308,20



Maintenance, Maintenance, Execute 0,00

No pictures to display

Bumper F, Crack, Le - Replace and paint 0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Dent(s), Acceptable 0,00

No pictures to display

Bumper grille F R, Crack, E - Replace 32,40



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Front end, Crack, Forfeit 99,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display