


**BMW 3: 1JAL805**

Vinnumber:	<b>WBA3Y110X0D450707</b>	Versionname:	<b>3 GRAN TURISMO 318d</b>
First Registrationdate:	<b>18/11/2014</b>	Fiscalpower:	<b>136PK</b>
Expertise Mileage:	<b>126324</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4806</b>
Maintenance:	<b>BINNEN 15000 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	<b>Tow bar removable</b>
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 427,36

**Door R L, Dent(s), Acceptable** 0,00

**Wing R L, Dent(s), Acceptable** 0,00



Door panel R R, Scratch(es), Acceptable

0,00



Wing R R, Dent(s), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R, Scratch(es), Acceptable

0,00



Tailgate, Scratch(es), Acceptable

0,00



Door F L, Repaired, P - Check

0,00



Alloy rim F L, Scratch(es), I - Repair

100,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), It - Spot repair

115,56



Seat cover F L, Worn, Acceptable

0,00

