



BMW 3: 1FVA243

Vinnumber:	WBA3K91070F932202	Versionname:	3 TOURING 316d 116PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	180544	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 29000KM	Parking lot:	4505
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 W Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1761,65
-------------------	----------------

Seat cover F L, Worn, Acceptable	0,00
----------------------------------	-------------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Wheel cover R L, Scratch(es), E - Replace

30,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Wheel cover R R, Scratch(es), E - Replace

30,00



Wing R R, Scratch(es), Acceptable

0,00



Door F R, Scratch(es), Acceptable

0,00



Wheel cover F L, Scratch(es), E - Replace

30,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing F L, Dent(s), LI - Repair and paint (complete)

220,18



Door R R, Scratch(es), Acceptable 0,00



Door panel F L, Hole, E - Replace 114,00



Bumper F L, Scratch(es), It - Spot repair 115,56



Bumper F R, Scratch(es), It - Spot repair 115,56



Ignition key, Missing, E - Replace 150,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wing F R, Dent(s), PDR - Paintless dent repair 63,00



Floor covering F L, Stain, Cleaning 25,00

